



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

November 26, 2007

Supervisor RRH

Mine Name: Wonder #2

Operator Name: Diversified Stone Products

Permit number: S/041/0025

Inspection Date: November 20, 2007

Time: 8:00 am

Inspector(s): Lynn Kunzler, DOGM

Other Participants: none

Mine Status: Inactive/reclaimed

Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls,
8. Soils
9. Revegetation

Evaluated	Comment	Enforcement
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Check on Site Reclamation.

Inspection Summary:

The Division received a phone call on November 15, 2007, indicating that equipment would be mobilized by the weekend and that the remaining reclamation work at the site would begin Monday morning (11/19/2007). This was confirmed via a phone call to Feller Stone (company hired to complete the reclamation work) on 11/16/2007. The operator called the Division office on 11/19/2007 indicating that that Feller had been delayed and that the equipment would arrive at the site Monday late, and that the work would begin Tuesday (11/20/2007). Upon arrival at the site, I found the reclamation work not completed, (highwall needs to be backfilled with the side cast material, the topsoil needs to be replaced, and the access road (spur) needs to be reclaimed). There was no equipment or personnel on site. I called Feller Stone to see where they were and was told that Russell Feller (the individual to do this work) had been sick, the equipment was still near the Utah/Idaho border, and that with the holiday this week, the they decided not to do anything this week and would begin on Monday November 26, 2007). I relayed this information the BLM office in Richfield.

Photos were taken to document site conditions.

Inspector's Signature LK

LK:pb

cc: Michael Jackson, BLM

O:\M041-Sevier\S0410025-Wonder2\inspections\Insp-11202007.docc